

**TASMA**  
**Two Meter Area Spectrum Management Association**  
**1439 W. Chapman Ave., PMB 90**  
**Orange, CA 92868**

Technical Committee Meeting Minutes  
Saturday, September 29th, 2007  
@  
Red Cross Santa Monica Chapter  
1450 Eleventh Street  
Santa Monica, CA 90404

**These Minutes Are Not Yet Approved**

1. the meeting was called to Order at approximately 10:00 AM.
2. Technical Committee Attendees:

Matt Lechliter	W6KGB	Chairman
Howard Brown	KG6GI	
Bob Dengler	NO6B	Ex-officio Member
- Guest Attendees:

Leon Brown	KC6JAR
------------	--------
3. The Minutes from the June 2nd, 2007 TC meeting were read and approved..
4. Continued Business from Previous TC Meetings:
  - a. **146.115 K6PSK** Hollywood Hills – The Committee, having received a letter from the coordinee that the repeater was sold 5 or 6 years ago to KE6TNM and having received no application for a new coordination, on a motion by Howard, KG6GI, approved termination of the K6PSK coordination (1-0-1).
  - b. **145.200 KD6KTQ** Juniper Hills – This is a new RFC (ref. 2007-172). This pair was previously coordinated to ‘Kit’ Clover, W9TTT and later to his spouse, Marvel Clover (WA6QDO) both of whom are SK. After discussion, the Committee, on motion by Howard, KG6GI approved this new coordination as filed (1-0-1).
  - c. **147.210 KK6SS** Apple Valley – This is a new RFC (ref. 2007-12). This RFC was tabled from previous meeting, awaiting specific frequency. The Committee reviewed frequency possibilities and decided that a frequency pair of 147.210/147.810 MHz might work. The committee, on motion by Howard, KG6GI, approved the coordination with a 12 month test period (1-0-1).
5. Test Coordination Reviews:
  - a. **144.505 KB6JAG/W6COH** Hemet –The Committee reviewed the test coordination but has been unable to determine that the repeater is operational. The Committee, on motion by Howard KG6GI, decided to query the application as to the repeater status (1-0-1).
  - b. **144.895 N6WZK** Mt. Wilson – he Committee reviewed the test coordination but has determined that the repeater is not operating with coordinated parameters.

The Committee, on motion by Howard KG6GI, approved termination of the test coordination (1-0-1).

- c. **145.200 WA6IRC** Contractor’s Point – The WA6IRC test coordination has proven to interfere with co-channel Arcadia repeater (N6AH). The Committee, on motion by Howard, KG6GI, approved the termination of the test coordination (1-0-1). Also see paragraph 6 and 7.m below.

6. New D-STAR RFC Applications:

The Committee reviewed the outstanding requests for D-STAR system coordination applications. The Committee decided to allocate the recently approved band plan changes to accommodate narrow bandwidth digital voice radios as follows:

System Call Sign	Location	Pair Frequencies
WA6IRC/A	Contractor’s Peak	145.605- MHz
W6CPA/A	Blue Ridge	145.585- MHz
W6HRO/A	Anaheim (KL6MF)	145.616- MHz
KB6HRO/A	Burbank (K6EJC	145.616- MHz
KC6RYZ/A	Keller Peak	145.595- MHz

7. Interference Complaints:

- a. **145.360 WB6YMH** Palos Verdes –The Committee has been advised that Skip, WB6YMH has relocated the repeater in question to Las Vegas and therefore terminates his interest in his coordination at 145.360 MHz (ref. 2007-25 and e-mail note of 9-26-2007, 9:29 PM). The Committee, on motion by Howard, KG6GI, approved termination of the coordination (1-0-1).
- b. **146.850 K6AER** Grissom Peak – Coordinee receiving interference from uncoordinated system, 146.850 KC6FLG\_at Mt. Wilson. As this is an interference claim between two repeaters, on coordinated and the other uncoordinated, it is the responsibility to KC6FLG to correct the interference situation. The Committee, on motion by Howard, KG6GI, voted to advise K6AER to bring the matter to the attention of the FCC if the situation persists (1-0-1).

7. New RFCs, updates and notifications:

- a. **146.895 K6SYV** Solvang – (ref. 2007-65b) This RFC advises TASMA of a change in ownership of the repeater. However, the RFC included only page 1 and did not include the required location and equipment information. The Committee, on motion by Howard, KG6GI, decided to request the applicant to provide the missing information (1-0-1).
- b. **147.210 K6SYV** Figueroa Mountain – (ref. 2007-65a) This RFC advises TASMA of a change in ownership of the repeater. However, the RFC included only page 1 and did not include the required location and equipment information. The Committee, on motion by Howard, KG6GI, decided to request the applicant to provide the missing information (1-0-1).
- c. **146.655 KF6VAQ** Moreno Valley – RFC Update (ref. 2007-66). This RFC involved changing the call-sign on the KF6VAQ repeater to Club call AB6MV.

The Committee, on motion by Howard, KG6GI, approved the RFC as filed (1-0-1).

- d. **144.895 N6WZK** Keller Peak – New RFC (ref. 2007-243). This RFC is for a new coordination for a repeater located at Keller Peak. The Committee, on motion by Howard, KG6GI, approved the RFC as filed with a 4 month test period (1-0-1).
- e. **147.225 W6OY** Moreno Valley – New RFC (ref. 2007-173). This new RFC requests a coordination on a pair that is consistent with the Band plan but reverse from already coordinated repeaters and therefore in inappropriate. Bob Dengler is to review the application and recommend an alternate, if possible, to the applicant. The Committee, on motion by Howard, KG6GI, agreed to advise the applicant that the frequencies won't work and that the location coordinates (lat/long) are in question (1-0-1). The application will be tabled and placed on the waiting list.
- f. **146.385 KE6ZTX** Keller Peak – RFC Update (ref. 2007-171b) – This RFC advises TASMA that they are requesting a reversal of their coordination pair to solve an interference problem with an adjacent repeater. This change will bring the pair in compliance with the Band plan. The Committee, on motion by Howard, KG6GI, approved the RFC as filed (1-0-1).
- g. **146.265 K6DLX** Willits Peak – RFC Update (ref. 2007-191 & 211) – This RFC update advises TASMA that the coordinee relinquishes the pair. The Committee, on motion by Howard KG6GI, approved termination of the coordination (1-0-1).
- h. **146.700 K4ELE/KB6TJJ** Sunset Ridge – Change of Ownership (ref. 2007-233) This RFC advised TASMA of a change in ownership of the repeater. The RFC was missing the location and technical information in its entirety. The Committee, on motion by Howard, KG6GI, decided to request the applicant to provide the missing information (1-0-1).
- i. **145.460 KQ6NO** Moorpark – New RFC (Ref. 2007-210). This RFC is for a new coordination for a repeater located at Camarillo/Moorpark. The Committee, on motion by Howard, KG6GI, approved the RFC as filed with a 6 month test period (1-0-1).
- j. **147.465 N6RDK/W6VLD** Huntington Beach – Change of Ownership (Ref. 2007-182b). This RFC appears to be an update changing the holder of the Coordination from the McDonnell-Douglas radio Club to the Boeing Employees Amateur Radio Society. The RFC was missing the technical information in its entirety. This information was last confirmed in 1999. The Committee, on motion by Howard, KG6GI, decided to request the applicant to provide the missing information (1-0-1).
- k. **145.615 K6EJC/KB6HRO/A** Burbank – New RFC. - This application (ref 2007-216b) is for a coordinated pair for a D-STAR system located in Burbank. The Committee, on motion by Howard, KG6GI, approved the application as filed on a frequency of 145.615 MHz (1-0-1).
- l. **145.615 KL7MF/W6HRO/A** Anaheim – New RFC. - This application (ref 2007-216a) is for a coordinated pair for a D-STAR system located in Anaheim. The Committee, on motion by Howard, KG6GI, approved the application as filed on a frequency of 145.615 MHz (1-0-1).

- m. **145.605 WA6IRC/A** Contractor's Point– New RFC. - This application (ref 2007-257) is for a coordinated pair for a D-STAR system located on Contractor's Point. The Committee, on motion by Howard, KG6GI, approved the application as files on a frequency of 145.605 MHz (1-0-1).
- n. **145.585 W6CPA/A** Blue Ridge – New RFC. - This application (ref 2007-258) is for a coordinated pair for a D-STAR system located on Blue Ridge. The Committee, on motion by Howard, KG6GI, approved the application as filed on a frequency of 145.585 MHz (1-0-1).
- o. **145.595 W6CPA/A** Keller Peak – New RFC. - This application (ref 2007-256) is for a coordinated pair for a D-STAR system located on Keller Peak. The Committee, on motion by Howard, KG6GI, approved the application as filed on a frequency of 145.595 MHz (1-0-1).

8. New Business

- a. **'Waiting List' Report.** – Due to lack of time the Waiting List was not reviewed.
- b. **Database Update Project** - Twenty (20) questionable coordinations were identified as a result of this years member recruitment program. In addition there were five actionable submittals received. These include:
  - i. Trustee's out of area – 6 occurrences
  - ii. Trustee's FCC address not current – 9 occurrences
  - iii. Trustee's name and call sign do not match – 2 occurrences
  - iv. Trustee's call not on record – 3 occurrences.
  - v. Miscellaneous Other – 5 occurrences
- c. **D-STAR / Auxiliary Frequency Pair Discussion** – See paragraph 6 above.

9. The meeting was Adjourned at approximately 2:00 PM.