

**TASMA**  
**Two Meter Area Spectrum Management Association**  
**1439 W. Chapman Ave., PMB 90**  
**Orange, CA 92868**  
Technical Committee Meeting Minutes  
Saturday, July 10, 2010

**THESE MINUTES ARE NOT YET APPROVED**

Agenda:

1. Meeting called to order by NO6B at 12:05 PM
2. Technical Committee members present:

Bob Dengler	NO6B	T.C. Chairman, Secretary
Rick Freidel	KB6OT	
Howard Brown	KG6GI	
Brian Roode	NJ6N	
  
- Visitors:

Darren Rumas	N6VGU
Ken Chafin	W6CPA
David Elder	KA6TBF
  
3. Reading of minutes from the May 29<sup>th</sup> 2010 TC meeting. Motion to accept by KB6OT, 2<sup>nd</sup> by KG6GI. Vote 3-0-0.
  
4. Interference complaints:
  - a. **147.765 (-) W6QFK** Santa Anita Ridge: interference to adjacent channel repeaters due to overdeviation & spurious emissions observed. NO6B received an e-mail from KA6UDZ, one of the repeater technicians stating that the trustee transfer for W6QFK is in process, & also requested information from our database in order to complete an RFC update form. NO6B will provide KA6UDZ with the requested information & follow up on the interference problem.
  
5. Old Business, RFCs, updates and notifications
  - a. Waiting list report.  
Coordination waiting list as of the beginning of the meeting:

<b>Date</b>	<b>Callsign</b>	<b>Location</b>
12/10/2007	N6HOG	La Crescenta (N6HOG QTH)
12/15/2008	W6CTR	Running Springs
4/3/2009	K6AMS	Running Springs
4/8/2009	KA6UAI	Palomar Mtn.
5/25/2009	KF6HKM	Contractor's Point
5/25/2009	KF6HKM	Oat Mtn.
6/5/2009	W6GAN	Sylmar
7/1/2009	W6ARB	Long Beach
8/10/2009	K6RRR	Mt. Otay (P25)
2/10/2010	K6JSI	Chuckwalla Mtn.
  
  - b. **146.820 (-) W6FNO** Onyx Peak – system observed non-operational: progress report. No additional correspondence received from W6FNO since the 11/2009 meeting, where it was reported that the W6FNO system was damaged by lightning. Per Committee decision at the 2/2010 meeting, an e-mail was sent to W6FNO on 4/11/2010 advising him that his Onyx Peak system needs to be put back on the air by no later than the August T.C. meeting. No response to the e-mail has been received.

- c. **146.355 (+) KB6LJO** Chuckwalla Mtn.: unable to access system. System tech. Letter sent to trustee advising he has 60 days to re-establish operations or the coordination will be terminated. No response received.

6. New Business

- a. **147.705 (-) N7RDA** Flint Peak: system observed operating from different location. N6VGU, contact for N7RDA advises that this repeater has been taken off the air. Motion by KG6GI, 2<sup>nd</sup> by KB6OT to terminate coordination. Vote 3-0-0.
- b. **147.705 (-) N7RDA** Oat Mtn: system observed operating from different location. N6VGU, contact for N7RDA advises that this repeater has been moved to Contractor's Point, and has submitted an RFC for this move. Due to interference complaints received from AF6D & AD6HK regarding this system, a motion from KG6GI, 2<sup>nd</sup> by KB6OT was made to table action on this RFC until the August T.C meeting. Vote 3-0-0..
- c. **446.46 (-) K6JSI** Greater LA Basin: new RFC.  
**447.58 (-) K6JSI** Greater LA Basin: new RFC.  
**447.64 (-) K6JSI** San Diego: new RFC.  
**448.06 (-) K6JSI** Greater LA Basin: new RFC.  
**448.80 (-) K6JSI** Vista: new RFC.  
**448.90 (-) K6JSI** San Fernando Valley: new RFC.  
**448.90 (-) K6JSI** San Diego: new RFC.  
**449.08 (-) K6JSI** Palomar Mtn.: new RFC.  
**449.12 (-) K6JSI** Escondido: new RFC.  
**449.16 (-) K6JSI** Greater LA Basin: new RFC.  
**449.50 (-) K6JSI** Pomona: new RFC.

None of the above RFCs were submitted with any grandfathering documentation. Per board/membership decision, the Technical Committee cannot process non-grandfathered (ordinary) coordinations at this time. However, SCRRBA advises that the 448.060 repeater is in fact coordinated by SCRRBA, which makes this application eligible for grandfathering. Motion by KG6GI, 2<sup>nd</sup> by NJ6N to issue coordination for 448.06 with provision that the actual system location will be published, as "Greater LA Basin" is too generalized; concurrence from K6JSI must be obtained before issuing final coordination. Vote 3-0-0. K6JSI will be asked to provide grandfathering documentation for the other systems. Remainder of the RFCs will be tabled until the next meeting.

- d. **145.480 (-) W6AM** Mt. Lukens: RFC update (change from private to open status). Motion by KG6GI, 2<sup>nd</sup> by NJ6N to ask applicant to submit a fully completed RFC form, as the one submitted only indicates the site name, frequency & open status. Vote 3-0-0.
- e. **147.390 (+) N1SAT** Claremont Mesa: new RFC. Motion by KG6GI, 2<sup>nd</sup> by NJ6N to deny coordination due to other systems in the area coordinated reverse pair of this frequency. Vote 3-0-0. Applicant will be asked if he wishes to be placed on the waiting list.
- f. **147.435 (-1.035) W6NUT**: RFC update: change in location from Contractor's Point to Santiago Peak. Motion by KG6GI, 2<sup>nd</sup> by KB6OT to issue test coordination ending 11/2010. Vote 3-0-0.
- g. **446.14 (-) WB6FMT** North San Diego county: new RFC. Applicant requests grandfather coordination & submitted supporting documentation in the form of a completed SCRRBA RFC dated 2/1997, copies of several e-mails between the applicant & SCRRBA, & a copied page from the 2003-2004 ARRL repeater directory showing a WB6FMT repeater on 446.140 that covers San Diego. Motion by KG6GI, 2<sup>nd</sup> by NJ6N to issue coordination with provision that the actual system location will be published, as "North San Diego County" is too generalized; concurrence from WB6FMT must be obtained before issuing final coordination. Vote 3-0-0.
- h. **445.34 (-) KC6JAR** Contractor's Point: new RFC. Submittal included a copy of SCRRBA coordination. Motion by KG6GI, 2<sup>nd</sup> by KB6OT to issue coordination. Vote 3-0-0.
- i. **447.48 (-) WB6IRC** Blue Ridge (D-Star): new RFC. RFC was withdrawn by W6CPA due to lack of grandfathering documentation.
- j. **449.92 (-) W6CPA** Blue Ridge: new RFC. RFC was withdrawn by W6CPA due to lack of grandfathering documentation.

7. NO6B called for adjournment at 2:55 PM.

Submitted by Bob Dengler, NO6B  
2010 TASMA Technical Committee Secretary