TASMA

Twin-band Area Spectrum Management Association 1439 W. Chapman Ave., PMB 90 Orange, CA 92868

Technical Committee Meeting Minutes

Saturday, January 24, 2015

Approved

1. Call to Order.

With quorum present, meeting called to order at 11:05am.

2. Attendance.

Sean, AJ6B Chuck, N6GYY
David, KA6TBF Nate, KI6IGR
Tony, KJ6UFG Benigno, KN6RW

3. Approval and any correction of minutes from the November 1, 2014 technical committee meeting.

MOTION to approve minutes by KI6IGR passed. 4-0-0.

- 4. Old Business:
 - a. <u>146.880(-) KK6JYT</u> Los Angeles: <u>RFC</u> 2014-032-T. New Repeater. Tabled from previous meeting for more information.
 MOTION to decline RFC due to overlapping coverage by KJ6UFG. 4-0-0
 - b. <u>147.075(+) KN6RW</u> Littlerock: <u>OOCP</u> 2014-036-T. Possible repeater location change. Unable to contact trustee. Possible off frequency. OOCP notice sent. Interference complaint unfounded, original complainant not responding, KN6RW updated contact information.
 - **c.** <u>147.420(146.475) AA6RJ</u> Palos Verdes: <u>OOCP</u> 2014-038-C. Reported running on reverse with simplex Echolink node. Contacted trustee with requested repeater changes.

Owner fixing repeater – sending updated RFC when back on air. Tabled to next meeting.

d. <u>144.505(+) W6COH</u> Hemet: <u>OOCP</u> 2014-040-T. Reported location change/operating from new location. Reported power output change. Tabled to gather further information.

Issue appears to be uncoordinated 2nd W6COH transmitter in simulcast.

5. Test Coordinations Not On The Air Yet: (in construction)

6. Test Coordinations On The Air:

a. <u>146.760(-) KD6QLT</u> Palm Springs: <u>RFC</u> Update 2013-065d-C. New repeater in test coordination test ending 3-2015.

No action required.

b. <u>145.260(-) AI6BX</u> Redlands: <u>RFC</u> 2014-028-D. New Repeater in test coordination ending in 3/2015.

No action required.

c. <u>147.645(-) K6RIA</u> Rialto: <u>RFC</u> 2014-029-D. New Repeater in test coordination ending in 3/2015.

No action required.

d. <u>146.025 (+) W6ECS</u> Hesperia: <u>RFC</u> 2014-035-D. New Repeater in test coordination ending in 3/2015.

No action required.

7. Coordination Waiting List:

	Date:	Expire:	Call Sign:	RFC:	Location:
a.	04/03/2009	12/2014	K6AMS	2009-040	Running Springs
b.	05/25/2009	12/2014	KF6HKM	2014-007(ud)	Contractor's Point
<i>c</i> .	05/25/2009	12/2014	KF6HKM	2014-007(ud)	Oat Mountain
d.	12/01/2012	3/2015	W6NUT	2012-009em	Contractor's Point

Waiting list applicants remain on the waiting list for one year per waiting list guidelines.

MOTION to remove expired waiting list RFCs by N6GYY. 4-0-0

8. New Business:

a. <u>147.330(+) XE2BNC:</u> *Tecate, Mexico*: <u>Interference Report</u> 2014-046-C: N6WYF on 147.945 MHz interferes on repeater input from XE2SI.

MOTION to send letter reminding repeater owners to watch their frequency drift and deviation by N6GYY. 4-0-0

b. <u>147.300(+)</u> K6VGP Otay: <u>RFC</u> 2014-042-T. New repeater.

MOTION to reject RFC due to inaccurate information on RFC. 4-0-0

c. <u>146.700(-) W7RT</u> Lake Havasu City, AZ: <u>RFC</u> 2014-047-C. New repeater.

Cross-coordination notification.

No action required.

d. <u>144.505(+) W6COH</u> North Mountain: <u>RFC</u> 2014-043-N. Second transmitter. Existing coordinated site 'Simpson Park'. MOTION to decline RFC due to overlapping coverage by KI6IGR. 4-0-0

- e. <u>147.615 (-) KC6BEU</u> Running Springs: <u>RFC</u> 2014-044-S. Trustee change. No action required.
- **f.** <u>145.440(-) KC6BEU</u> Palomar Mountain: <u>RFC</u> 2014-044-S. Trustee change. No action required.
- **g.** <u>146.160(+) KI6DB</u> Mission Viejo: <u>OOCP</u> 2014-049 Reported off the air. MOTION to start OOCP process for being off the air by KI6IGR. 4-0-0
- **h.** <u>146.160(+) KA6TBF</u> Mission Viejo: <u>RFC</u> 2014-048-C. New repeater. MOTION to issue test coordination pending 8.g outcome above by KJ6UFG. 4-0-0
- i. Fusion/WIRES-X Technology discussion.
- 9. Sub-Committee Business:
 - a. None.
- 10. Next Committee Meeting: March 7, 2015.
- 11. Adjournment.

MOTION to adjourn by KI6IGR at 12:35pm.

Definitions:

RFC – Request for Coordination OOCP – Out of Coordinated Parameters

Created by:

Sean Reigle, AJ6B, Technical Committee Secretary

Agenda published 1/9/2015 SR Minutes draft published 2/7/2015 SR